BREATHE HEALTHIER®

GeneralAire®

Humidifier

Residential Whole-House (GFI #5144)

GeneralAire® Model 1042LH

Evaporative Humidifier

Control Indoor Humidity.

Installing a GeneralAire® Whole House Humidifier can reduce allergy and asthma symptoms, minimize risk of infection, protect valuables (such as furniture, woodwork and musical instruments) *and* save you money.



LIMITED WARRANTY 5 years



How The 1042LH Works:

Your furnace sends warm air through a water-soaked Vapor Pad® inside your humidifier, where it absorbs additional moisture. Newly-moistened air is then distributed throughout your home to provide healthier indoor air for you and your family.

Details inside or go to: www.generalfilters.com/model1042LH

Maintenance

Maintenance of your new GeneralAire® 1042LH Legacy Series Flow Through Humidifier is minimal. To ensure peak performance and reliable operation, simply perform the following maintenance: change your Vapor Pad® and clean mineral deposits from the water distribution trough and drain pan. The following solution is recommended: 1/2 water and 1/2 vinegar. Go to www.generalfilters.com / support / video library to view a video demonstrating how to change your Vapor Pad®.

Install A Humidifier In Your Home To:

Protect Your Family's Health:

Low humidity is where viruses can thrive and cause your throat and nasal passages to dry. This leads to nose bleeds, increased risk of infection, colds, flu and other respiratory ailments. Dry air can trigger asthma and allergy symptoms. Air that's too dry causes dry/itchy/cracked skin.

Protect Your Valuables:

Dry air in your home can cause expensive artwork, wood flooring, cabinets, furniture and musical instruments to crack. Dry air increases annoying static shocks that can damage electronics.

Save Money:

Since dry air can cause woodwork to crack, resulting gaps in windows & doors let cold outside air in. In addition, dry air feels colder. Take the chill out with a 1042LH. Turn your thermostat down and save money.

Why A Whole-House Unit?

- Treats Your Whole House 24 / 7 / 365
- Requires Minimal Maintenance
- Out of Site
- Quiet

General Filters Inc.

General Filters, Inc.
43800 Grand River Avenue
Novi, Michigan 48375 USA
Toll Free: (866) 476-5101
www.generalaire.com

Canadian General Filters Limited

Canadian General Filters, Ltd.
400 Midwest Rd.
Toronto, ON M1P3A9 Canada
Toll Free: (888) 216-9184
www.generalaireiaq.ca

BREATHE HEALTHIER®
GeneralAire®

Humidifier
Residential Whole-House (GFI #5144)
GeneralAire® Model 1042LH
Evaporative Humidifier



Designed & Assembled in Michigan, USA

Cover Removal Screws (2)
- Remove screws, lift off water distribution tube and trough to replace Vapor Pad®.

Metal Water Distribution Tube
- Delivers water to the water distribution trough.

Cover
- Made with an ultra-violet stable automotive-grade plastic for long-lasting durability.

Inspection Window
- Simply remove the GeneralAire® badge.

Sturdy Drain Pan

Quiet Operation
- You'll forget it's there!

Water Distribution Trough
- Distributes water evenly throughout Vapor Pad® for maximum evaporation.

Stainless Steel Water Distribution Tube
- Brings (hot or cold) water into the unit.

Damper Control Knob
- Open during use.

Water Drain Tube
- Water is automatically drains from your humidifier.



Included
MHX3C Manual Humidistat

Your new 1042LH comes with an easy-to-use MHX3C humidistat. Simply turn the dial to the left for more humidity, or to the right for less.



Replacement Vapor Pad®
- GFI #7002: 990-13
- For optimal performance, replace your Vapor Pad® at the beginning of each heating season.


Easy to install. *Easier* to maintain.

The Comprehensive Approach to Indoor Air Quality

Creating a healthy indoor air environment requires a comprehensive approach; one that eliminates harmful pollutants and sources of discomfort in your home. Humidity control, air purification, and particulate removal are equally important components of that plan.

Install a Second Wind™ UV Air Purifier to degrade bacteria, germs, viruses, mold, mildew, VOC's, and other infectious diseases. The Second Wind™ 2414-Z features photocatalytic oxidation with singlet oxygen to provide germIcidal purification throughout your home while also eliminating stubborn odors.

Contact your local contractor to learn more about how to create a healthier and more comfortable home for you and your family. And visit us at www.generalfilters.com for more on indoor air quality.



Learn more about the 2124-Z ▸

Last Updated: 12-2021 GFI LIT#: 1042LH Our Brands GeneralAire Second Wind General GarBer
Download online at: www.generalfilters.com/literature/spec/submittal. All information subject to change without notice.